



The Copper fill tube on SSI / LEI CO2 tubes becomes too short after 2 refills. This Cu tube is brazed onto the mirror mount so to do a 3rd refill the entire mirror mount assembly must be replaced.